


Install a PoleMaster onto a CEM120 Mount

The PoleMaster adapter for CEM120 (3337-120) comes with an adapter Mounting Plate, a USB Bridge Board with a pair of washers and a USB cable.




Insert two brass washers between the USB Bridge Board and the PoleMaster USB port. Insert the small locking screws. Push the USB Board down and tighten the screws.



Plug in the USB cable.




Align the PoleMaster to the Mounting Plate. Make sure that the USB port of the PoleMaster is facing the cutout of the Mounting Plate. Use three long M3 screws coming with your PoleMaster to secure it onto the Mounting Plate.




Plug in the USB Bridge Board onto the PoleMaster USB port. Do not fully press it down.



Unthread the front Polar Axis Cover from the CEM120 RA axis. Remove the Cable Management Input Panel.



Insert the PoleMaser with Mounting Plate into the mount RA axis from the front. Thread the USB cable through the RA axis and plug the other end to the rare socket of iPolarScope on the Cable Management Input Panel. Reattach Input Panel.



Rotate the PoleMaster to a proper position. Lock it by evenly tightening three Mounting Plate Locking Screws clockwise.

